

Inspection Photos
Operator: Dugan Production
Location/API #: 067-06498
Date: 9-16-2019



Photo 1. View of the project area from the well pad entrance facing center. Well pad is deeply rutted and water is ponding on working area. Stabilization measures are needed.



Photo 2. View of rutting up to 12 inches deep on the well pad access road.



Photo 3. View of the southern project area from the eastern corner facing westward. Vegetation is progressing with perennial grasses such as smooth brome within the interim reclamation areas.



Photo 4. View of the western project area on right, and mowed reference area on left, facing northward. Reference area is comprised of irrigated grass field grasses such as orchard grass and smooth brome.