

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-09816
Date: 9-16-2019



Photo 1. View of the project area from the southwest corner facing center.



Photo 2. View of the southern fill slope facing eastward. Approximately 1000 musk thistles observed within the outer revegetation areas.



Photo 3. View of erosional channel approximately 2 feet wide and deep within the southern project area.



Photo 4. View of extensive (approx. 100 feet long and 50 feet wide) sediment discharge and channeling within the southern project area.



Photo 5. View of reference area vegetation, east of the project area, facing northward.