

Inspection Photos

09/20/2019

Operator: BISON OIL & GAS II LLC # 10661

Location ID: 454591

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 1: Photo taken from the south end of the location, facing north. Photos 1-3 provide an overview of the location from north, northeast to east. Photos show operator appears to be conducting interim reclamation.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the north end of the location. Photo shows containers have been placed in secondary containment. Photo also shows stained soils observed in previous inspections have not been sufficiently cleaned/treated and/or removed.

Inspection Photos

Operator Name: BISON OIL & GAS II LLC # 10661

Location ID: 454591



Photo 5: Previous inspections documented insufficient, or illegible labeling on tanks identifying contents. Photo shows labeling remains insufficient.



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 7: Photo taken from the north end of the location. Photo shows container previously identified has not been placed in secondary containment. Photo also shows required labeling identifying contents remains missing.



Photo 8: Continued from photo 7



Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 9: Photo shows required labeling on tanks remains missing.



Photo 10: See comments under photo 9.



Inspection Photos

Operator Name: BISON OIL & GAS II LLC # 10661

Location ID: 454591



Photo 11: See comments under photo 9..



Photo 12: Photo taken from the northwest corner of the location, facing south. Photos show operator appears to be conducted interim reclamation.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 13: Photo taken from the northwest corner of the location, facing southeast. Photos show operator appears to be conducted interim reclamation.



Photo 14: Photo of wattles within ditch. BMP appears to have been installed in accordance with good engineering practices.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 15: Photo taken from the northeast end of the location. Photo shows operator appears to have installed a sediment trap. BMP appears to be sufficient and proper functioning condition to meet the site's conditions post interim reclamation.



Photo 16: Photo taken from the east end of the location facing west. Photos show operator appears to be conducted interim reclamation.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 17: Photo taken from the southeast end of the location. Photo shows contractor on site installing stormwater BMPs.



Photo 18: Photo taken from the south end of the location, facing north. Photo shows compaction alleviation in process. Rule 1003.c requires locations to be cross-ripped to a minimum depth of 18 inches. Photo shows location has only been ripped once in one direction. Contractor on site stated that the location was not planned to be cross-ripped in accordance with 1003.c.



Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 454591



Photo 19: Photo shows ripper teeth used to conduct compaction alleviation. Photo shows used to conduct compaction alleviation are not sufficient in size to rip to a minimum depth of eighteen (18) inches in accordance with 1003.c.



Photo 20: Continued from photo 19. Photo shows teeth used to conduct compaction alleviation was approximately 1 foot in length.