

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/16/2019

Document Number:

680305578

FIELD INSPECTION FORM

Loc ID 312242 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55030
Name of Operator: MCCARTNEY ENGINEERING LLC
Address: 4251 KIPLING ST STE 575
City: WHEAT RIDGE State: CO Zip: 80033

Findings:

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
McCartney, Ron	(303) 830-7208	ron@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219789	WELL	SI	08/01/2016	OW	075-07216	RICE 2	UN

General Comment:

[Routine Site Inspection 2019](#)
[Note to Operator: Please read FIR completely and send Form 42 response when all CA's have been performed for follow-up reinspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	Lease road is heavily rutted, exhibiting erosion and lack of BMP's.		
Corrective Action:	Repair and maintain lease roads per Rule 604 series.	Date:	10/14/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		Date:
Corrective Action:			
Good Housekeeping:			
Type	DEBRIS		
Comment:	Remove cement from previous work-over conversion to IJ, dated 04/16/2019.		
Corrective Action:	Remove surface debris/trash per Rule 604 series.	Date:	09/27/2019
Type	UNUSED EQUIPMENT		
Comment:	Well has been converted to IJ. Remove PJ from location.		
Corrective Action:	Remove unused equipment per Rule 603 series	Date:	12/16/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Other	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 219789 Type: WELL API Number: 075-07216 Status: SI Insp. Status: UN

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 04/16/2019

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: Well has been converted to IJ. Update well file/well status/production reports.

Corrective Action: Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment:

Corrective Action: Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been converted to IJ since April 2019.
NOTE TO OPERATOR: Update/change well status on COGCC database.

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	Fail			

Comment: [Use BMP's for erosion management.](#)

Corrective Action: **Lease road is exhibiting rutting from erosion. Repair (fill ruts) and grade, maintain lease road per Rule 1002 series.**

Date: 10/14/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402178820	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939055
680305579	Wellhead - PJ (unused equipment)	09-11-2019 048.JPG
680305580	Debris	09-11-2019 050.JPG