

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2019

Submitted Date:

09/13/2019

Document Number:

689703530**FIELD INSPECTION FORM**Loc ID 335850 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290456	WELL	WO	11/02/2007	SI	045-14110	N.PARACHUTE WF510B J22A 596	WO
290457	WELL	WO	10/10/2007	SI	045-14111	N.PARACHUTE WF510A J22A 596	WO

**General Comment:****COGCC Inspection Report Summary**

On Friday 09/13/2019 at approximately 1330 hrs, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC, N.PARACHUTE-65S96W 22NWSE, at Location #335850 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Well shelter roof on edge of location.

Comply with Rule 603.f.

C.A. Date 10/16/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Well shelter roof on edge of location.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/16/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 290456 Type: WELL API Number: 045-14110 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Form 21 doc# 401562389

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 290457 Type: WELL API Number: 045-14111 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Form 21 doc# 401562424

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass					
		Compaction	Pass			
Ditches	Pass					
Gravel	Pass					
		Ditches	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402178787	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939018">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939018</a>
689703531	Inspection 689703530 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939013</a>