

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2019

Submitted Date:

09/17/2019

Document Number:

696101310

FIELD INSPECTION FORM

Loc ID 428456 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428457	WELL	PR	04/01/2019	OW	123-35367	North Platte 14-36	SI
428616	WELL	PR	05/01/2019	OW	123-35441	Latham F-J-1HZ	SI
428618	WELL	PR	10/01/2018	OW	123-35443	North Platte X-D-35HZ	PR

General Comment:

This is a WELL & BATTERY inspection.
3: Wells
(1: Producing | PR ; 2: Shut-In | SI).
Battery: Active.

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type CONTAINERS		
	Comment:		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment:		
	Corrective Action:		
			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Oily waste. Stained soil appear at crude oil tank loadline area. Stained soil appears between 2nd - 4th tanks from east going west. Refer to Rule 907.e. Remove or remediate stained soil at crude oil tank loadline area. Comply w/ Rule 907.e. See photos #6, 7.		
Corrective Action:	Remove or remediate stained soil at crude oil tank loadline area. Comply w/ Rule 907.e.		Date: <u>10/17/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: 		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type WELLHEAD		
	Comment: 3: Wellheads ; Iron panel		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by metal berms		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 3		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 15		
Comment:	4: ECD scrubbers 5: Chemical pumps, plastic drums, drip containment 2: Metal tanks, drip containment (Methanol) 4: Metal tanks, drip containment (Coolant)		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Controls crude oil tanks VOCs. Pilots: ON		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	CONCRETE SUMP/VAULT		,

Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)	60 Bbls.						
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ crude oil tanks & produced H2O tanks.				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	300 BBLS	STEEL AST				
Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ crude oil tanks & produced H2O vaults.				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	10	400 BBLS	STEEL AST		40.352353,-104.389715		
Comment:		Equalizer lines connect 8/10 crude oil tanks.				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ produced H2O tanks / vaults.				Date:	
Corrective Action:						Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 428457 Type: WELL API Number: 123-35367 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In. | SI.
Observed production valves closed at well.

Corrective Action: _____ Date: _____

Facility ID: 428616 Type: WELL API Number: 123-35441 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In. | SI.
Observed production valves closed at well.

Corrective Action: _____ Date: _____

Facility ID: 428618 Type: WELL API Number: 123-35443 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/17/2019 at approximately 12:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /14-36 Location ID: 428456 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Producing PR ; 2: Shut-In SI. Battery: Active.</p> <p>1: Corrective Actions observed. 1.) Oily waste. Stained soil appear at crude oil tank loadline area. Stained soil appears between 2nd - 4th tanks from east going west. Refer to Rule 907.e. Remove or remediate stained soil at crude oil tank loadline area. Comply w/ Rule 907.e. Corrective Action date: 10/17/2019. See photos #6, 7.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402179838	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939859
696101311	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939850