

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

679705531**FIELD INSPECTION FORM**

Loc ID 335897	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>110 W 7TH STREET</u> City: <u>FORTH WORTH</u> State: <u>TX</u> Zip: <u>76102</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292855	WELL	PR	09/01/2017	GW	103-11090	PICEANCE CREEK UNIT 197-34B3	PR
292858	WELL	PR	09/01/2017	GW	103-11089	PICEANCE CREEK UNIT 197-34B9	PR
292860	WELL	PR	01/01/2019	GW	103-11088	PICEANCE CREEK UNIT 197-34B5	PR
292871	WELL	PR	03/01/2017	GW	103-11087	PICEANCE CREEK UNIT 197-34B4	PR
292873	WELL	PR	09/01/2017	GW	103-11086	PICEANCE CREEK UNIT 197-34B7	PR
292887	WELL	PR	09/01/2017	GW	103-11085	PICEANCE CREEK UNIT 197-34B2	PR
292888	WELL	PR	09/01/2017	GW	103-11084	PICEANCE CREEK UNIT 197-34B1	PR
292889	WELL	PR	09/01/2017	GW	103-11083	PICEANCE CREEK UNIT 197-34B6	PR
293965	WELL	PR	09/01/2017	GW	103-11146	PICEANCE CREEK UNIT 197-34B10	PR

General Comment:

COGCC Inspection Report Summary.

On 9-23-2019 at approximately 13:00, inspector Rick Moran, conducted a routine well inspection at XTO Energy pad Piceance Creek Unit 197-34B in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705531.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well headers.		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Two containers of MC MX 6-2719			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 2			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID:	292855	Type:	WELL	API Number: 103-11090 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292858	Type:	WELL	API Number: 103-11089 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292860	Type:	WELL	API Number: 103-11088 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292871	Type:	WELL	API Number: 103-11087 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292873	Type:	WELL	API Number: 103-11086 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292887	Type:	WELL	API Number: 103-11085 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292888	Type:	WELL	API Number: 103-11084 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	292889	Type:	WELL	API Number: 103-11083 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		

Facility ID:	293965	Type:	WELL	API Number:	103-11146	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gradient Terraces	Pass					
Gravel	Pass	Gravel	Pass			
Retention Ponds	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705544	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945557