

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

679705532**FIELD INSPECTION FORM**

| | | | | |
|---|--------------------------------|---|-------------------|---|
| Loc ID 413472 | Inspector Name: Moran, Rick | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>110 W 7TH STREET</u> City: <u>FORTH WORTH</u> State: <u>TX</u> Zip: <u>76102</u> | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|---------|
| Dooling, Jessica | 970-769-6048 | Jessica_Dooling@xtoenergy.com | |
| Reid, Van | | van_reid@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 412692 | WELL | PR | 09/01/2017 | GW | 103-11536 | PICEANCE CREEK UNIT 197-34A9 | PR |
| 412693 | WELL | PR | 09/01/2017 | GW | 103-11537 | PICEANCE CREEK UNIT 197-34A8 | PR |
| 412694 | WELL | PR | 02/01/2018 | GW | 103-11538 | PICEANCE CREEK UNIT 197-34A7 | PR |
| 412695 | WELL | PR | 09/01/2017 | GW | 103-11539 | PICEANCE CREEK UNIT 197-34A6 | PR |
| 412696 | WELL | PR | 09/01/2017 | GW | 103-11540 | PICEANCE CREEK UNIT 197-34A5 | PR |
| 412697 | WELL | PR | 09/01/2017 | GW | 103-11541 | PICEANCE CREEK UNIT 197-34A4 | PR |
| 412698 | WELL | PR | 09/01/2017 | GW | 103-11542 | PICEANCE CREEK UNIT 197-34A3 | PR |
| 412699 | WELL | PR | 09/01/2017 | GW | 103-11543 | PICEANCE CREEK UNIT 197-34A2 | PR |
| 412700 | WELL | PR | 09/01/2017 | GW | 103-11544 | PICEANCE CREEK UNIT 197-34A1 | PR |
| 415496 | WELL | PR | 09/01/2017 | GW | 103-11637 | PICEANCE CREEK UNIT 197-34A10 | PR |

General Comment:

COGCC Inspection Report Summary.

On 9-23-2019 at approximately 13:30, inspector Rick Moran, conducted a routine well inspection at XTO Energy pad Piceance Creek Unit 197-34A in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705532.

LocationOverall Good: ☒

| | | | |
|----------------------|------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------|---------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Well headers. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Separator | # 1 | | |
| Comment: | In building. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | Three containers of MC MX 6-2719 with secondary containment. | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 412692 | Type: | WELL | API Number: | 103-11536 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412693 | Type: | WELL | API Number: | 103-11537 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412694 | Type: | WELL | API Number: | 103-11538 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412695 | Type: | WELL | API Number: | 103-11539 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412696 | Type: | WELL | API Number: | 103-11540 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412697 | Type: | WELL | API Number: | 103-11541 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412698 | Type: | WELL | API Number: | 103-11542 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412699 | Type: | WELL | API Number: | 103-11543 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 412700 | Type: | WELL | API Number: | 103-11544 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing WellComment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 415496 | Type: | WELL | API Number: | 103-11637 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing WellComment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |
| Ditches | Pass | | | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679705545 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945558 |