

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

679705533**FIELD INSPECTION FORM**

Loc ID 336007	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>110 W 7TH STREET</u> City: <u>FORTH WORTH</u> State: <u>TX</u> Zip: <u>76102</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299793	WELL	PR	06/01/2013	GW	103-11420	FREEDOM UNIT 197-33B7	PR
299794	WELL	PR	06/01/2013	GW	103-11421	FREEDOM UNIT 197-33B8	PR
299795	WELL	PR	06/01/2013	GW	103-11422	FREEDOM UNIT 197-33B9	PR
299796	WELL	PR	06/01/2013	GW	103-11423	FREEDOM UNIT 197-33B10	PR
299797	WELL	PR	06/01/2013	GW	103-11424	FREEDOM UNIT 197-33B6	PR
299798	WELL	PR	06/01/2013	GW	103-11425	FREEDOM UNIT 197-33B5	PR
299799	WELL	PR	06/01/2013	GW	103-11426	FREEDOM UNIT 197-33B4	PR
299800	WELL	PR	07/01/2018	GW	103-11427	FREEDOM UNIT 197-33B2	PR
299801	WELL	PR	01/01/2017	GW	103-11428	FREEDOM UNIT 197-33B1	PR
300296	WELL	PR	06/01/2013	GW	103-11433	FREEDOM UNIT 197-33B3	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 9-23-2019 at approximately 14:00, inspector Rick Moran, conducted a routine well inspection at XTO Energy pad Freedom Unit 197-33B in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705533.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Two containers of MC MX 6-2719		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Well headers.		
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299793	Type:	WELL	API Number:	103-11420	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299794	Type:	WELL	API Number:	103-11421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299795	Type:	WELL	API Number:	103-11422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299796	Type:	WELL	API Number:	103-11423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299797	Type:	WELL	API Number:	103-11424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299798	Type:	WELL	API Number:	103-11425	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299799	Type:	WELL	API Number:	103-11426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299800	Type:	WELL	API Number:	103-11427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			

Facility ID:	299801	Type:	WELL	API Number:	103-11428	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

Facility ID:	300296	Type:	WELL	API Number:	103-11433	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			
Slope Roughening	Pass					
Retention Ponds	Pass					

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705546	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945559