

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

679705534**FIELD INSPECTION FORM**
 Loc ID 336018 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293172	WELL	PR	03/01/2018	GW	103-11097	FREEDOM UNIT 197-33A3	PR
293173	WELL	PR	06/01/2015	GW	103-11101	FREEDOM UNIT 197-33A5	PR
293174	WELL	PR	06/01/2013	GW	103-11100	FREEDOM UNIT 197-33A4	PR
293176	WELL	PR	06/01/2013	GW	103-11099	FREEDOM UNIT 197-33A1	PR
293178	WELL	PR	03/01/2018	GW	103-11098	FREEDOM UNIT 197-33A2	PR
299330	WELL	PR	03/01/2017	GW	103-11399	FREEDOM UNIT 197-33A7	PR
299331	WELL	PR	03/01/2017	OW	103-11400	FREEDOM UNIT 197-33A9	PR
299332	WELL	PR	03/01/2017	GW	103-11401	FREEDOM UNIT 197-33A8	PR
412690	WELL	PR	03/01/2017	GW	103-11535	FREEDOM UNIT 197-33A6	PR

**General Comment:**[COGCC Inspection Report Summary.](#)[On 9-23-2019 at approximately 14:15, inspector Rick Moran, conducted a routine well inspection at XTO Energy pad Freedom Unit 197-33A in Rio Blanco county.](#)[No corrective actions were identified.](#)[This is a summary of inspection report 679705534.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well headers.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Three container of MC MX 6-2719 with secondary containment.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 11		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293172	Type:	WELL	API Number:	103-11097	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	293173	Type:	WELL	API Number:	103-11101	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	293174	Type:	WELL	API Number:	103-11100	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	293176	Type:	WELL	API Number:	103-11099	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	293178	Type:	WELL	API Number:	103-11098	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299330	Type:	WELL	API Number:	103-11399	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299331	Type:	WELL	API Number:	103-11400	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299332	Type:	WELL	API Number:	103-11401	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			

Facility ID:	412690	Type:	WELL	API Number:	103-11535	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift.

Corrective Action:		Date:	
--------------------	--	-------	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Retention Ponds	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705547	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945560</a>