

**Inspection Photos**  
**Location Name: DYER-66N64W /2NENW**  
**Location #: 302248**



**Photo #1**  
**Dyer 2-21 (05-123-28012) Wellsite**  
**Shut-In | SI**  
*prior insp.*



**Photo #2**  
**Dyer 2-21, 2-24, 2-25 Battery**  
**Shut-down | Inactive**

**Inspection Photos**  
**Location Name: DYER-66N64W /2NENW**  
**Location #: 302248**



Colorado Oil & Gas Conservation Commission  
40.52243, -104.51749, 1457.0m, 171°  
09/09/2019 03:34:14 PM

**Photo #3**  
**Dyer 2-21, 2-24, 2-25 Separators**  
**Shut-down | Inactive**  
**Weeds**  
*prior insp.*



Colorado Oil & Gas Conservation Commission  
40.52229, -104.51754, 1433.0m, 202°  
09/23/2019 02:55:54 PM

**Photo #4**  
**Dyer 2-21, 2-24, 2-25 Separators**  
**Shut-down | Inactive**  
**Weeds appear mitigated**