

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

695101400

FIELD INSPECTION FORM

Loc ID 308531 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273504	WELL	PR	07/12/2007	GW	071-08177	BEARLY 24-29	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			
Produced Water	WELLHEAD	>= 5 bbls			
Comment:	PHOTO 3: APPEARS THAT PACKING WAS LEAKING ON WELLHEAD (NOT THERE IS NO LEAK AT TIME OF INSPECTION). IMPACTED AREA EXTENDS FROM WELLHEAD TO SOUTHWEST APP. 123'. PHOTO 4: ANOTHER PATH EXTENDING FROM WELLHEAD WEST AND THEN SOUTH FOR APP. 93'. PHOTO 5: PHOTO SHOWING THAT THERE HAS BEEN OTHER EVENTS AS YOU CAN SEE THE WHITE CHALKY STAINING BEYOND THE CURRENT WET SOIL. WHITE CHALKY STAINING EXTENDS PAST CURRENT WET SOIL APP.18'.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. CA DATE 9-25-19.			Date:	09/25/2019

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PLUMBED TO SURFACE		
Corrective Action:			Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Inspected Facilities

Facility ID: 273504 Type: WELL API Number: 071-08177 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Complaint

Comment:

THIS INSPECTION IS IN RESPONCE TO A COMPLAINT. DOC# . ON THE FIRST INVESTIGATION i FOUND THAT THE OPERATOR HAD A TEST COMPRESSOR AT THE START OF THE ROW TO THIS LOCATION. AT TIME OF INITIAL INVESTIGATION THE OPERATOR WAS IN THE PROCESS OF SHUTTING DOWN THE COMPRESSOR. THEY SAID TEST WAS NOT GOOD THEY WHERE REMOVING THE COMPRESSOR. THAT COMPRESSOR WAS NOT ASSOCIATED WITH THIS WELL, IT WAS CONNECTED TO A GATHERING LINE NOT ASSOCIATED WITH THIS LOCATION. I SPOKE WITH COMPLAINTANT AND HE STATED THAT THE NOICE HAS BEEN REDUCED SINCE HIS COMPLAINT WAS FILED.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101401	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946093