

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

687905536**FIELD INSPECTION FORM**

Loc ID 333838 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216230	WELL	PR	08/25/2017	GW	067-07836	BRADFIELD CH 1	PR
295867	WELL	PR	05/05/2008	GW	067-09554	BRADFIELD CH 3	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report.

Location

Lease Road:			
Type	Access		
comment:	Gravel road access from county road.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels are posted on tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on signs.	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjacks.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire around location.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	Electric VFD drive motors on pumpjack and LRP with MCC.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 2	
Comment:	(1) standard pumpjack (1) Linear Rod Pump.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	PVC bradenhead access.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	On duell separator stack.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Wellheads with valve assembly and block valves.	
Corrective Action:		Date:
Type: Flow Line	# 11	
Comment:	2-3" steel flowlines from wellheads to separator. 2-2" steel flowlines from separator blowdown to produced water tank. 2-2" steel flowlines from separator dump valves to offsite produced water gathering system. 2-3" steel flowlines from separator to meter house. 2-3" steel flowlines merging into 1-4" steel flowline to offsite dogleg.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 216230 Type: WELL API Number: 067-07836 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 295867 Type: WELL API Number: 067-09554 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gravel	Pass					
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			
Gradient Terraces	Pass	Gravel	Pass			

Comment: [Stormwater BMP's appear to be working at time of inspection. Cut slope has established vegetation.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905542	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946188