

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

696101336

FIELD INSPECTION FORM

Loc ID 305248 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275957	WELL	SI	05/01/2019	OW	123-22707	CECIL 41-2	SI

General Comment:

This is a WELL & BATTERY inspection.
Well is Shut-In | SI.
Battery: Shut-down | Inactive.
Centralized Battery serves 2 Location IDs (305248, 305249).
(2: wells ; Shut-In | SI).

Follow-up to Field Inspection Report Doc. #696101270 dated 09/09/2019.

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment:	<input style="width: 50%;" type="text"/>	
Corrective Action:	<input style="width: 50%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/19/2019. This insp: * Weeds NOW appear mitigated. See photos 1, 2.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 90%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type WELLHEAD		
	Comment: Iron panel		
Corrective Action:			Date:
	Type TANK BATTERY		
	Comment: Braided wire.		

Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs. Pilots: OFF Shut-down.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (305248, 305249).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.522251,-104.508769	
Comment:						
Corrective Action:				Date:		

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ produced H2O tank.						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS			
Comment:						
Corrective Action:				Date:		

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ crude oil tank.						
Corrective Action:				Date:		

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:	
Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 275957 Type: WELL API Number: 123-22707 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut at well.
Last prod: 04/2019.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 09/23/2019 at approximately 15:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: CECIL-66N64W /2NENE Location ID: 305248 Well Name: Cecil 41-2 API: 05-123-22707 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Shut-In SI. Battery: Shut-down Inactive Centralized Battery serves 2 Location IDs (305248, 305249).</p> <p>Follow-up to Field Inspection Report Doc. #696101270 dated 09/09/2019. 1 of 1: Corrective Actions addressed. 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/19/2019. * Weeds NOW appear mitigated. See photos 1, 2.</p> <p>NO: New Corrective Actions observed on this Field Inspection Report.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101337	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946210