

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

696101342

**FIELD INSPECTION FORM**

Loc ID 302324 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10261  
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC  
Address: 730 17TH ST STE 500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		wellinspections@bayswater.us	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297978	WELL	PR	10/01/2017	OW	123-28147	DYER 2-25	SI

**General Comment:**

This is a WELL inspection.  
Well is Shut-In | SI.  
Battery: Shut-down | Inactive.  
Centralized Battery serves 3 Location IDs (302248, 302246, 302324).  
(3: wells ; Shut-In | SI).

Refer to Field Inspection Doc. #696101330 and/or Location ID #302248 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report Doc. #696101278 dated 09/09/2019.

This report supersedes Field Inspection Report Doc. #696101334 dated 09/23/2019. Summary Date has been amended.

Location			
<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment:	<input style="width: 50%;" type="text"/>	
Corrective Action:	<input style="width: 50%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Prior insp: Unused Equipment at wellsite (Chemcial drum & rack). Refer to Rule 603.f. Remove unused equipment at wellsite. (Chemcial drum & rack). Comply w/ Rule 603.f. Corrective Action date: 10/09/2019  This insp: * Unused equipment at wellsite. (Chemcial drum & rack). Now appears removed. See photos 1, 2.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 80%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:	Refer to Field Inspection Doc. #696101330 and/or Location ID #302248 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type:	#	
Comment:	Refer to Field Inspection Doc. #696101330 and/or Location ID #302248 for Battery / Facility, Equipment info.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.522285,-104.517823
Comment:	Centralized Battery serves 3 Location IDs (302248, 302246, 302324). Refer to Field Inspection Doc. #696101330 and/or Location ID #302248 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 297978 Type: WELL API Number: 123-28147 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.  
Observed production valves shut at separator.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 09/23/2019 at approximately 14:38 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: BAYSWATER EXPLORATION &amp; PRODUCTION LLC                      Location Name: DYER /2-25                      Location ID: 302324                      Well Name: Dyer 2-25                      API: 05-123-28147                      Location County: Weld County, Colorado                      Weather: Dry</p> <p>While there, I observed:                      Well(s) - 1: Shut-In   SI.                      Battery: Shut-down   Inactive                      Centralized Battery serves 3 Location IDs (302248, 302246, 302324).                      (3: wells ; Shut-In   SI).</p> <p>Refer to Field Inspection Doc. #696101330 and/or Location ID #302248 for Battery / Facility, Equipment info.</p> <p>This report supersedes Field Inspection Report Doc. #696101334 dated 09/23/2019. Summary Date has been amended.</p> <p>Follow-up to Field Inspection Report Doc. #696101276 dated 09/09/2019.                      1 of 1: Corrective Actions addressed.                      1.) Unused Equipment at wellsite (Chemcial drum &amp; rack).                      Refer to Rule 603.f.                      Remove unused equipment at wellsite. (Chemcial drum &amp; rack).                      Comply w/ Rule 603.f.                      Corrective Action date: 10/09/2019                      * Unused equipment at wellsite. (Chemcial drum &amp; rack). Now appears removed.                      See photos 1, 2.</p> <p>NO: New Corrective Actions observed on this Field Inspection Report.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101343	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946257</a>