

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

679705559

**FIELD INSPECTION FORM**

Loc ID 316373 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORTH WORTH State: TX Zip: 76102

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Arauzo, Steven		steven.arauza@state.co.us	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Heil, John		john.heil@state.co.us	
Reid, Van		van_reid@xtoenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270456	WELL	PR	07/01/2019	GW	103-10401	YELLOW CREEK FEDERAL 3-45-1	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-24-2019 at approximately 15:45, inspector Rick Moran, conducted a routine inspection at Yellow Creek Federal 3-45-1 in Rio Blanco county.

The following compliance issues were observed:

- 1) Well head sign missing "911". Photo 5. Complete by 10-24-2019.
- 2) Contact COGCC EPS in reference to the line leak. Photo 4, 6, 7, 8, Complete by 9-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705559.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<a href="#">"911" missing on well head sign.</a>		
Corrective Action:	<a href="#">Install sign to comply with Rule 210.b.</a>		Date: <u>10/24/2019</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Produced Water			
Comment:	<p>On approaching the location the inspector observed water flowing down the lease road. On arrival at the location water was observed bubbling up from the ground near the pig station. The inspector estimated it was flowing out at 1 bbl every 3 to 5 minutes. XTO Energy was called in reference to the leak on their emergency number at 970-675-4117 @ 15:36. At 15:46 two XTO representatives arrived at the location and immediately accessed the situation and started procedures to stop the leak. The leak appeared to fully stop at 16:06. The water flowed approximately 200 feet down hill from the source.</p>		
Corrective Action:	<a href="#">Contact COGCC EPS staff regarding Rule 906.c.</a>		Date: <u>09/26/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		

Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Equipment building.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Container of methanol with secondary containment.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.991250,-108.371520
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	400 BBLs	STEEL AST		39.991250,-108.371520
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 270456 Type: WELL API Number: 103-10401 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705560	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946270">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946270</a>