

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2019

Submitted Date:

09/18/2019

Document Number:

699300206**FIELD INSPECTION FORM**

Loc ID 311312 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241289	WELL	PR	12/15/1976	OW	123-09077	JACK BERGER A 6	IO

**General Comment:**

## Location

**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	At time of inspection wellhead sign is legible but faded. Emergency contact number is barely legible. No corrective action at this time but sign will need addressed soon.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds overgrown on wellsite		
Corrective Action:	Comply with Rule 603.f	Date:	09/28/2019
Type	OTHER		
Comment:	Stained soil around flow line riser		
Corrective Action:	Comply with Rule 907.e	Date:	10/18/2019
Type	OTHER		
Comment:	flow line has possible leak		
Corrective Action:	Comply with Rule 605.d	Date:	10/18/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	OTHER		
Comment:	Electrical transformers, breaker panel and meter. Fabricated steel pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
-----------------	-----	--	-----------------

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical transformers, breaker panel and meter.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241289 Type: WELL API Number: 123-09077 Status: PR Insp. Status: IO**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Report shows well as producing, at time of this inspection well appears to be inactive the electric panel appears to be shut off.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 9/18/2019 at approximately 1200hrs. Inspector Robbie Revas, Conducted an on-site inspection at the Jack Berger A #6 KP Kauffman, at</p> <p>API #05-123-09077 in Weld County Colorado. While there, I observed a wellsite report show it as PR at the time of this inspection it appears to be inactive the electric panel appears to be shut off. See photo #5.</p> <p>During this inspection no compliance issues were observed:</p> <p>At time of inspection wellhead sign is legible but faded. Emergency contact number is barely legible. No corrective action at this time but sign will need addressed soon. See photo #1</p> <p>Housekeeping: Weeds are overgrown on wellsite. Comply with Rule 603.f 10 days for weeds. CA date 9/28/2019. See photos #1, 2, 3 and 4.</p> <p>Housekeeping: Stained soil around flow line. Comply with Rule 907.e 30 days to remove stained soil. CA date 10/18/2019. See photo #6</p> <p>Mechanical issue: Appears Flow line has possible leak. Comply with Rule 605.d Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. 30 days unless leak is found. Immediate call to operator if leak is found and 24 hours to fix the leak or isolate leak. CA date 10/18/2019 See photo #7</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure that compliance issues are addressed to comply with COGCC Rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402181458	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941138</a>
699300207	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941134</a>