

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

694900433**FIELD INSPECTION FORM**

Loc ID 334790 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211592	WELL	TA	01/01/2017	OW	045-07353	SHIDELER 19-15	TA
271161	WELL	PR	04/01/2013	GW	045-09845	SHIDELER 30-2 (O19E)	PR
276985	WELL	PR	05/01/2019	GW	045-10562	SHIDELER 19-10 (O19E)	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 9/24/19 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus 019E, at Location # 334790 in Garfield County, Colorado.

While there, I observed Normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	chemical tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 211592 Type: WELL API Number: 045-07353 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 271161 Type: WELL API Number: 045-09845 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date: Facility ID: 276985 Type: WELL API Number: 045-10562 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Gravel				
Ditches		Ditches				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900440	694900433	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946361