

Inspection Photos

API: 05-071-09062

Operator: ARP PRODUCTION COMPANY

WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo) There were a few weeds wilting but most were not treated. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 2. There is List B noxious weeds growing along the main & access road to the location. (Canada thistle shown in photo) Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 3. Sediment has filled into the check dams. Erosion is occurring down and along the side of the road. Corrective action was not properly completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 4. Facing southwest toward the location. There are numerous noxious weeds at the location. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 5. Erosion is occurring down the cut slope from the diversion ditch.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 6. Wattles are displaced along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 7. There are erosion channels developing along the cut slope which need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 8. Rock rip/rap was installed at the end of the diversion ditch however, sediment has already filled in the diversion ditch from erosion of the cut slope. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 9. There are noxious weeds (Musk thistle) growing at the top of the cut slope. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 9/23/2019

Inspection Photos



Photo 10. There is plastic netting that remains in a pile at the top of the cut slope. This is debris that must be removed.

