

Inspection Photos

API: 05-071-07915

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 1. There are noxious weeds along the main road which have not been controlled. (Musk thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 1. The road has been graded to allow stormwater to drain off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 3. Culvert has been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 4. It appears a new culvert was installed at this point in the road. There is no outlet protection which is shown in the right photo. Disturbance area must be reclaimed.

Lat/Long:37.00845,-104.84245



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 5. This culvert is partially filled in with sediment and damaged.

Lat/Long:37.00817,-104.84711



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 7. Facing toward the cut slope. Red arrow points to List B noxious weeds. The cut slope is not stabilized. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019

Inspection Photos



Photo 8. Facing toward the southwest cut slope. Red arrow points to List B noxious weeds. The cut slope is not stabilized. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 9/23/2019