

Inspection Photos

API: 05-071-09051

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09051 | Date: 9/23/2019

Inspection Photos



Photo 1. The outlet culvert at the location has no BMP's to prevent erosion. This photo was from previous inspection and was not inspected.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 9/23/2019

Inspection Photos



Photo 1. The inlet culvert near the location is partially filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 9/23/2019

Inspection Photos



Photo 3. Facing toward the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 9/23/2019

Inspection Photos



Photo 4. There are List B noxious weeds along the south side of the location. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 9/23/2019