

Inspection Photos

API: 05-071-06867

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the access road near the building near the location. (Canada thistle shown in photo)

Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019

Inspection Photos



Photo 2. Facing toward the location. Vegetation has not established throughout the location. There are Lis B noxious weeds at the location. (Photo shows Bull thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019

Inspection Photos



Photo 3. Sediment has filled into the wattles.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019

Inspection Photos



Photo 4. There are sign stormwater is flowing underneath the wattle. Wattles were not properly trenched into the ground. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019

Inspection Photos



Photo 5. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 9/23/2019