

WELL SITE INSPECTION FORM

2

WELL NAME Routh Co. 1-15
 OPERATOR Motiva Energy
 LOCATION SENECA, 7N, 87W
 FIELD Wolf Mtn

API NUMBER 05 - 107 - 6136
 PERMIT NUMBER _____
 COUNTY Routh
 INSPECTOR Kathy Buehl

AL/PA/DA INSPECTION RESULTS:

PASS(Y) Y FAIL(N) _____ DATE 10/4/86

WELL STATUS:

FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____

DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES ☒ NO _____

PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____

SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____

HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Visited well previously - Plugged but not restored.
Has been restored now according to man at Wolf Mtn
Ranch. OK by them (checked up)



00221567