

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2019

Submitted Date:

09/26/2019

Document Number:

698600147**FIELD INSPECTION FORM**Loc ID 320260 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADDBA ENERGY SEARCH CO INCAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stonehocker, Mark		markstonehocker@gmail.com	
Hickey, Mike		michael.hickey@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203279	WELL	PA	02/26/2015	OW	001-08788	WIERMAN 6	PA

**General Comment:**

This is an orphaned well inspection. Inspection completed to document removal of (2) risers at the production location and removal of remaining flow lines.

Inspection may also identify possible task required for final closure/release of location.

See link at end of report for path to downloadable pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Production location was located off the intersection of Holly and 152nd street.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Emergency Contact Number:</b>	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date:	<input type="text"/>

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Property is fenced with post and wire fencing.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 0		
Comment:	(2) steel above ground risers location on old production facility. All other equipment has been previously removed.		
	The (2) identified risers and lines were excavated and removed from location.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203279 Type: WELL API Number: 001-08788 Status: PA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>Daily note from Wierman #6 riser and flow line abandonment.</p> <p>9/06 – Inspection completed to verify and document location prior to riser and flow line abandonment. Site currently has (2) above ground risers on production facility. All other equipment has been removed with nothing noted above ground.</p> <p>GPS location of risers is 39.972057/-104.924823. Approximate GPS of end point at removed separator based on historic documents is 39.972135/-104924481. With total removal of flow lines planned GPS data is for historic value only.</p>	stjohnw	09/25/2019
<p>Daily note from Wierman #6 riser and flow line abandonment.</p> <p>9/11 – Inspection completed to document riser and flow line abandonment. Excavate at risers. Both lines run towards old separator site. Continue to excavate and find end points of lines. Lines completely removed.</p> <p>During end point excavation additional risers discovered at separator site. Lines appear to run towards old tank battery. Lines excavated and removed.</p> <p>Unearthed (2) 3' and (2) 1' poly lines while excavating. Lines belong to previously plugged and abandoned wells tied to the production location and were capped and abandoned in place. Contractor excavated lines to boundaries. The lines have been cut and removed from location. The Remainder of the line capped and left in place.</p>	stjohnw	09/25/2019
<p>Daily note from Wierman #6 riser and flow line abandonment.</p> <p>9/16 – Inspection completed to document riser and flow line abandonment. All Identified flow lines and risers have been excavated and removed from location. All trenching has been backfilled and site has been leveled. Site is ready for final reclamation.</p>	stjohnw	09/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600148	Riser and flow line removal photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947854">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947854</a>