

Inspection Photos  
Location Name: Newlander Pit  
Location ID 114274



Photo 1 – Location photo



Photo 2 – Location photo; fiberglass partially buried produced water tank on site

**Inspection Photos**  
**Location Name: Newlander Pit**  
**Location ID 114274**



**Photo 3 – Location photo**



**Photo 4 – Stained soil at separator**

**Inspection Photos**  
**Location Name: Newlander Pit**  
**Location ID 114274**



**Photo 5 – Stained soil under fire tube**



**Aerial Imagery**  
**Location Name: Newlander Pit**  
**Location ID 114274**



**Photo 6 – 1993 aerial imagery**



**Aerial Imagery**  
**Location Name: Newlander Pit**  
**Location ID 114274**



**Photo 7 – 2002 aerial imagery**



**Aerial Imagery**  
**Location Name: Newlander Pit**  
**Location ID 114274**



**Photo 7 – 2008 aerial imagery**



Aerial Imagery  
Location Name: Newlander Pit  
Location ID 114274




Photo 9 – 2018 aerial imagery

