

Inspection Photos
Location Name: Ocoma 31-27
Facility ID: 250003



Photo # 1 Wellhead & Sign

Inspection Photos
Location Name: Ocoma 31-27
Facility ID: 250003




Photo #2 Active leak at the casing collar

Photo #3 Active leak at the Meco regulator stainless fitting.