

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/26/2019

Document Number:

679601660

FIELD INSPECTION FORM

Loc ID 432487 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432488	WELL	PR	12/02/2013	OW	123-37130	Tateyama 15U-434	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused risers. See attached photo.		
Corrective Action:	Comply with Rule 603.f.		Date: 10/26/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:			Date:

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Equipment not anchored. See attached photo.		
Corrective Action:	Comply with Rule 603.h.(1)C		Date: 10/26/2019
Type: Ancillary equipment	# 3		
Comment:	Sounds wall (E) of pumpjack, 2 methanol containers in self containment.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		
Comment:	Anchored; ACCORDING TO COGCC MAPS, LOCATION IS IN FLOOD PLAINS.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		
Comment:	Anchored; ACCORDING TO COGCC MAPS, LOCATION IS IN FLOOD PLAINS.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.580600,-104.641600
Comment: Anchored; ACCORDING TO COGCC MAPS, LOCATION IS IN FLOOD PLAINS.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 432488 Type: WELL API Number: 123-37130 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday, September 26, 2019 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at TATEYAMA15U-434 (PDC Energy), at location #: 4342487 in WELD COUNTY Colorado. While there, I observed producing facility. During this inspection the following possible compliance issues were observed: 1. Appears that horizontal separator is not anchored. Location is in flood plains according to COGCC maps. COMPLY WITH RULE 603.H.(1).C. (Corrective Action Date: October 26, 2019) See attached photo #6. 2. Unused (LO/TO) risers near separator. No indication on tags that they will be used for future use. COMPLY WITH RULE 603.F. (Corrective Action Date: October 26, 2019) See attached photo #7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	09/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601661	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948152