

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-09839
Date: 9-16-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope facing southward. Revegetation is progressing with grasses such as smooth brome and western wheatgrass.



Photo 3. View of salt cedar tree within the western fill slope, needs to be controlled.



Photo 4. View of reference area vegetation, north of the project area, facing northward. Comprised of irrigated grass fields such as smooth brome and wheat grasses.