

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-06933
Date: 9-16-2019



Photo 1. View of the southern fill slope from the southwestern edge facing eastward. Revegetation is comprised of tall shrubs such as rubber rabbitbrush and fourwing salt bush, with grazed herbaceous understory.



Photo 2. View of grazed vegetation within the southern project area.



Photo 3. View erosional channeling, approximately 10 inches wide and 6 inches deep within the southern project area.



Photo 4. View of erosional channel, approximately 2 feet wide and deep, within the southern project area.



Photo 5. View of Russian knapweed and erosional channeling within the southern project area.



Photo 6. View of reference area vegetation, north of the project area, facing westward. Comprised of open pinyon juniper woodland, with native shrubby/herbaceous understory.