

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**Location/API #: 067-09838**  
**Date: 9-16-2019**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope facing southward. Revegetation is approximately continuous with surrounding irrigated grass field.



Photo 3. View Russian thistle and musk thistles within the southeastern project area.



Photo 4. View of reference area vegetation, west of the project area, comprised of irrigated grass field, grasses mowed and not in identifiable condition.