



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Bradenhead		# 1		
Comment:	NOT PLUMBED TO SURFACE			
Corrective Action:				Date:
Type: Ancillary equipment		# 1		
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 217689 Type: WELL API Number: 071-06468 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSP. DOC# 687902583, CORRECTIVE ACTION HAS BEEN ADDRESSED.	beardsit	09/26/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101428	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948577">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948577</a>