

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2019

Submitted Date:

09/26/2019

Document Number:

699300262**FIELD INSPECTION FORM**
 Loc ID 317781 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239961	WELL	SI	09/01/2018	GW	123-07749	DECHANT-STATE 2	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	OTHER		
Comment:	WH appears to be leaking from packing around tubing.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/11/2019

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	YES		
Comment:	Packing around Tubing on WH appears to be leaking		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC. Comply with Rule 912.b	Date:	09/27/2019

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 239961 Type: WELL API Number: 123-07749 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

COGCC Inspection Report Summary

On Thursday 9/26/2019 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Dechant State #2 KP Kauffman, at API #05-123-07749 in Weld County Colorado.

While there, I observed SI wellsite.

During this inspection the following possible compliance issue was observed:

Mechanical Issue: WH packing leaking around tubing.

Comply with Rule 605.d CA date 10/11/2019 see photos #2 and 3.

Venting or Flaring Natural Gas: Gas being vented or flared during non-upset condition without prior approval from COGCC. Comply with Rule 912.b CA date 9/27/2019 See photos #2 and 3.

Location is dry, weather is clear.

I called the emergency number and spoke to Laura and she said she would get an operator out to take care of the issue.

A follow up on this site inspection needs to be conducted to ensure that compliance issues are addressed to comply with COGCC Rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

User

revasr

Date

09/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300263	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948654