

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2019

Submitted Date:

09/26/2019

Document Number:

693200413

FIELD INSPECTION FORM

Loc ID 316373 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORTH WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Moran, Rick		rick.moran@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
XTO		COGCCInspectionReports@wpenergy.com	All Inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270456	WELL	PR	07/01/2019	GW	103-10401	YELLOW CREEK FEDERAL 3-45-1	EG

General Comment:

COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on September 25, 2019. In response to FIU inspection 679705559 and Form 19, document 402190122

Inspected Facilities

Facility ID: 270456 Type: WELL API Number: 103-10401 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 3" Material: Poly
 Variance: No Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No
 Coatings: No H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC FIU Staff observed water flowing down the lease road. On arrival at the location water was observed bubbling up from the ground near the pig station. COGCC staff contacted operator and flowline was shut in.
 Operator found a 2" hole in the 3" Shawor Poly water line
 Provide Root Cause when information becomes available. Via Form 4 and email to Western Integrity inspector
 Provide annual pressure test results for 3" water flowline and location flowlines. Via Form 4 and email to Western Integrity inspector
 Contact Western Integrity inspector to witness pressure test before returning flowline into service

Corrective Action:

Date: 10/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200414	XTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948647