

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-06266
Date: 9-11-2019



Photo 1. View of the project area from the southern corner facing center.



Photo 2. View of what appears to be surface owner equipment stored on the western portion of the well pad.



Photo 3. View of remediation area within the western project area facing northwestward. Area needs revegetation.



Photo 4. View of remediation area within the southwestern project area facing southward. Area needs revegetation.



Photo 6. View of reference area vegetation east of the project area, largely comprised of sagebrush shrubland and open juniper woodland.