

Inspection Photos
Operator: BP America
Location/API #: 067-07590
Date: 9-11-2019



Photo 1. View of the release area facing upslope. Vegetation is largely comprised of annual covercrop wheat (brown) and kochia (green).



Photo 2. View of road created to remediate the release, needs to be reclaimed.



Photo 3. View of Russian knapweed at bottom of slope to access point for release, needs to be controlled.



Photo 4. View of wattle debris within the well pad area.



Photo 5. View of example of trash and debris within the project area.



Photo 6. View of holes within the project area. Fencing is not sufficient to mitigate wildlife risk, and holes need to be filled.



Photo 7. View of area within the eastern project area that was recently disturbed and appears to be seeded.



Photo 8. Birdseye view of grass seedlings observed within eastern revegetation area.



Photo 9. View of release area on hill slope. Geogrid material is installed in portions of slope and appears to be functioning at this time.



Photo 10. Birdseye view of vegetation on slope, largely comprised of weedy annual kochia, and annual covercrop wheatgrass. Cracking observed in many places of the soil appear to indicate stabilization concerns on slope.



Photo 11. Birdseye view of perennial grasses growing within a portion of the release area.



Photo 12. Birdseye view of annual weeds such as kochia, Russian thistle, and field bindweed within release area.



Photo 13. View of disturbance area downstream from release at irrigation canal that is adjacent to BIA 111 Road. Revegetation does not appear to be progressing here and needs to be re-seeded. Bare soils need erosion controls.



Photo 14. View of straw blanket on bank at location detailed in Photo 13. Vegetation appears to be progressing on this bank, through the blanket material.



Photo 15. View of reference area for the well pad facing eastward. Vegetation is comprised of pinyon juniper woodland.