

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/27/2019

Document Number:

693200415

FIELD INSPECTION FORM

Loc ID 334069 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
		COGCC.inspections@caerusoilandgas.com	All Piceance inspections
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262866	WELL	PR	09/17/2002	GW	045-08064	SHIDLER 1-7 (G1)	EG
268506	WELL	PR	07/08/2004	GW	045-09268	HMU 1-6D (G1)	EG
282079	WELL	PR	08/25/2006	GW	045-11633	SHIDLER FEDERAL 1-9 (G1SW)	EG
282080	WELL	PR	08/26/2006	GW	045-11632	SHIDLER FEDERAL 1-2C (G1SW)	EG
282081	WELL	PR	07/21/2006	GW	045-11631	SHIDLER 1-1C (G1SW)	EG
466951	SPILL OR RELEASE	AC	09/03/2019		-	SHIDLER-68S93W 1SWNE	AC

General Comment:

COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray
Engineering Integrity Inspection performed on September 27, 2019
Inspection is to witness integrity testing of 4" and 6" Flexsteel flowlines that run from G1SW location to the H2SW location, approximately 1-1/2 miles

Inspected Facilities				
Facility ID: <u>262866</u>	Type: <u>WELL</u>	API Number: <u>045-08064</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>268506</u>	Type: <u>WELL</u>	API Number: <u>045-09268</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282079</u>	Type: <u>WELL</u>	API Number: <u>045-11633</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282080</u>	Type: <u>WELL</u>	API Number: <u>045-11632</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282081</u>	Type: <u>WELL</u>	API Number: <u>045-11631</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>466951</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

Flowline			
#1	Type: <u>Non-Well Site</u>	1 of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Non-Well Site</u>	Size: <u>6"</u>	Material: <u>Other</u>	
Variance: <u>No</u>	Age: <u>1-5 Yrs</u>	Contents: <u>Produced Water</u>	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed: <u>Yes</u>	Test Result: <u>Pass</u>	Charted: <u>Yes</u>	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation	<input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair	<input type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>	30-minute pressure test, 6" Flex steel flowline. Test performed with Air. Start with 104.6psi ended with 104.2psi		
<u>Corrective Action:</u>		<u>Date:</u>	
#2	Type: <u>Non-Well Site</u>	1 of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Non-Well Site</u>	Size: <u>4"</u>	Material: <u>Other</u>	
Variance: <u>No</u>	Age: <u>1-5 Yrs</u>	Contents: <u>Produced Water</u>	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed: <u>Yes</u>	Test Result: <u>Pass</u>	Charted: <u>Yes</u>	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation	<input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair	<input type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>	30-minute pressure test, 4" Flex steel flowline. Test performed with Air. Start with 103.7psi ended with 103.5psi		

Corrective Action:		Date:	
--------------------	--	-------	--

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200416	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948898