

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/27/2019

Document Number:

679705607**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
316645 \_\_\_\_\_ Moran, Rick \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |
| Sanford, Anita  |              | atlx@chevron.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 290916      | WELL | PR     | 03/01/2018  | OW         | 103-11028 | M.C. HAGOOD B 1A | PR          |
| 422682      | WELL | PR     | 10/01/2016  | OW         | 103-11870 | MC HAGOOD B2     | PR          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-26-2019 at approximately 16:50, inspector Rick Moran, conducted a routine inspection at Chevron well M.C. Hagood B 1A and B 2 in Rio Blanco county.

The following compliance issues were observed:

1) "911" missing on well head signs. Photos 2 & 3. Complete by 9-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705607.

**Location**Overall Good: ☒

|                      |            |       |  |
|----------------------|------------|-------|--|
| <b>Signs/Marker:</b> |            |       |  |
| Type                 | WELLHEAD   |       |  |
| Comment:             |            |       |  |
| Corrective Action:   |            | Date: |  |
| Type                 | CONTAINERS |       |  |
| Comment:             |            |       |  |
| Corrective Action:   |            | Date: |  |

Emergency Contact Number:

Comment: "911" missing on well head sign.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 09/26/2019

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Ancillary equipment | # 2   |       |                 |
| Comment:                  | Two containers of corrosion inhibitor with secondary containment. |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Deadman # & Marked  | # 4   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Submersible Pump    | # 2   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 290916 Type: WELL API Number: 103-11028 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on subpump.

Corrective Action:

Date:

Facility ID: 422682 Type: WELL API Number: 103-11870 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on subpump.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms            | Pass            |                         |                       | Material Handling And Spill Prevention | Pass                     |         |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679705608    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948989">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948989</a> |