

Inspection Photos
Loc#452011
Operator: Terra
Inspection: #692401312
Inspection Date: 9/23/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from access road entry to Southeast. Arrow indicates cattle on site.

8/30/ 9/23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#2:
Overview of Location from top of topsoil stockpile to Southeast.

8/30/ 9/23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#3:
View along access road entry BMPs



Photo#4:
View along access road entry BMPs.

8/30/ 9/23, 2019



Photo#5:
Site degradation is occurring.

8/30/ 9/23, 2019




Photo#6:
Fill slopes are not stable.

8/30/ 9/23, 2019



Photo#7:
Fill slopes are not stable



Photo#8:
Fill slopes are not stable

8/30/ 9/23, 2019



Photo#9:
Slopes are not stable.



Photo#10:
Slopes are not stable

8/30/ 9/23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#11:
Slopes are not stable.

8/30/ 9/23, 2019



Photo#12:
Fill slopes populated with ruderal weeds.

Photo#13:
Fill slopes populated with ruderal weeds.

8/30/ 9/23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#14:
Noxious weeds on site.



Photo#15:
Noxious weeds on site

8/30/ 9/23, 2019



Photo#16:
Slopes are not stable.



Photo#17:
Slopes are not stable.

8/30/ 9/23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#18:
View of cuttings trench from Southeast to Northwest
end. Conductor cuttings in foreground.

8/30/ 9/23, 2019



Photo#19:
View of cuttings trench from Northwest to
Southeast end.



Photo#20:

Cut slope above cuttings trench is not stable. Circled area indicates where slope is less steep & cattle were watering

8/30/ 9/23, 2019



Photo#21:

Cut slope above cuttings trench is not stable.



Photo#22:

Cut slope above cuttings trench is not stable. Circled area indicates where slope is less steep & cattle were watering

8/30/ 9/23, 2019



Photo#23:

Cut slope above cuttings trench is not stable.



Photo#23:
View over cuttings at Southeast end of trench to cut
slope.

8/30/ 9/23, 2019



Photo#24:
Evidence of cattle inside cuttings trench area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU-31-17 Loc#452011



Photo#25:
Conductors set; not covered to prevent ingress by wildlife.

8/30/ 9/23, 2019



Photo#26:
Conductors set; not covered to prevent ingress by wildlife.