

KP Kauffman - COGCC Inspection Photos
Location: Charter Schneider Tank Battery
Facility ID #444630
REM #9522



View of excavation (flowlines exposed in walls/ view west).



Cut ends of flowlines exposed in excavation (view to west).

KP Kauffman - COGCC Inspection Photos
Location: Charter Schneider Tank Battery
Facility ID #444630
REM #9522



View of excavation (flowlines exposed) looking south.



View of excavation (flowlines exposed) looking NW.

KP Kauffman - COGCC Inspection Photos
Location: Charter Schneider Tank Battery
Facility ID #444630
REM #9522



East side of excavation, tanks and equipment on location.



Flowline segments cut out/ removed from excavation.