

Inspection Photos
Operator: Kinder Morgan
Location/API #: 083-06649
Date: 9-18-2019



Photo 1. View of the project area from the eastern edge facing center.



Photo 2. View of the southeastern project area from the eastern edge facing southward. Portions of reclamation area are recently disturbed and need revegetation.



Photo 2. View of what appears to be pipeline corridor where vegetation is cleared. Area needs revegetation.



Photo 3. View of reference area vegetation comprised of dryland grass field with herbaceous species such as smooth brome (*Bromus inermis*), crested wheatgrass (*Agropyron cristatum*), and western wheatgrass (*Pascopyrum smithii*).