

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/27/2019

Submitted Date:

09/27/2019

Document Number:

687905576**FIELD INSPECTION FORM**
 Loc ID 325935 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215590	WELL	PR	10/25/1989	GW	067-07195	STREETER B 1	PR

General Comment:
[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access through locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Cattle panels around wellhead.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Bradenhead	# 1			
Comment:	PVC bradenhead access.			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On separator stack.			
Corrective Action:				Date:
Type: Flow Line	# 4			
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215590	Type:	WELL	API Number:	067-07195	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Gradient Terraces	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905577	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4949628