

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2019

Submitted Date:

09/28/2019

Document Number:

696101351**FIELD INSPECTION FORM**Loc ID 306508 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289303	WELL	PR	06/01/2019	OW	123-24807	WILHITE 30-34	SI

General Comment:

This is a WELL inspection.
Well: Shut-In | SI.
Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (310319, 306508).
(Well(s): 2 ; Shut-In | SI).

Refer to Field Inspection Doc. #696101349 and/or Location ID #310319 for Battery /
Facility, Equipment info.

Follow-up to Field Inspection Report Doc. #696101237 dated 08/27/2019.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/09/2019.</p> <p>This insp: * Weeds at wellsite appear mitigated. See photos #1, 2.</p>		
Corrective Action:			Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Doc. #696101349 and/or Location ID #310319 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		

Comment:	Appears plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type:	#			
Comment:	Refer to Field Inspection Doc. #696101349 and/or Location ID #310319 for Battery / Facility, Equipment info.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.540096,-104.592901
Comment:	Centralized Battery serves 2 Location IDs (310319, 306508). Refer to Field Inspection Doc. #696101349 and/or Location ID #310319 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	289303	Type:	WELL	API Number:	123-24807	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In SI. Observed Hi/Lo motor valve closed at separator. COGCC records indicate last Prod: 07/2019. Form 21 Doc #401814562, Approved MIT done: 10/23/2018.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 09/27/2019 at approximately 16:58 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WILHITE-67N64W /30SESW Location ID: 306508 Well Name: Wilhite 30-34 API: 05-123-24807 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Shut-In SI. Hi/Lo motor valve shut at separator. Battery: Shut-down Inactive</p> <p>Centralized Battery serves 2 Location IDs (310319, 306508). (Well(s): 2 ; Shut-In SI).</p> <p>Refer to Field Inspection Doc. #696101349 and/or Location ID #310319 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #696101237 dated 08/27/2019.</p> <p>During this inspection the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/09/2019. * Weeds at wellsite appear mitigated. See photos #1, 2.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101352	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4949919