

Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



40.03937, -108.94499, 5326.7ft, 6°
09/27/2019 03:31:24 PM

Photo 1. Location.



Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



Photo 2. North of location.

Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



40.03983, -108.94466, 5330.7ft, -164°
09/27/2019 03:33:39 PM

Photo 3. North side of tanks.

Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



Photo 4. Tank holes.



Photo 5. Tank hole.

Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



Photo 6. Separator leak – 9/27/2019



Photo 7. Separator leak – 11/06/2018

Taiga Mountain 6-22
API: 05-103-08920
Inspection: 679705629



Photo 8. Well head.



Photo 9. Well head gas leak.

Gas leak