

Location			
Lease Road:			
Type	Access		
comment:	dead weeds all along acces road		
Corrective Action:	Comply with Rule 603.f		Date: 07/23/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Dead weeds completly covering electric panel		
Corrective Action:	Comply with Rule 603.f		Date: 07/23/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric panel		

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241290 Type: WELL API Number: 123-09078 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/24/19 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site Follow up inspection at the Mahoney #2 KP Kauffman, at API #05-123-09078 in Weld County Colorado. While there, I observed Wellsite. During this inspection the following possible compliance issues were observed: No current MIT submitted, Comply with Rule 326.b Produce well after performing successful mechanical integrity test per Rule 326.b or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. CA date 10/24/19 Access road: Rule 603.f Weeds completely overgrown on access road has not been addressed and are now dead this Compliance issue is delinquent per Doc. #693500607 CA date 7/23/2019 See photo #3 Weeds: Rule 603.f Weeds around electric panel have not been addressed and are now dead this Compliance issue is delinquent per Doc. #693500607 CA date 7/23/2019 See attached photo # 4. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402187850	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946283
699300244	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946273