

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 1 PH and PU. WH sign**



**Photo 2 Mechanical issue Braden head 1/4 hole open on 2" bushing.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 3 WH approx. 90ft from resident**

**Photo 4 WH approx. 100ft from resident**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 5 entrance to PU in barb wire fence**



**Photo 6 Barb wire fence with walk in opening.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



Colorado Oil and Gas Conservation Commission  
Oct 1, 2019 10:42:29

**Photo 7 loc pic**



Colorado Oil and Gas Conservation Commission  
Oct 1, 2019 10:43:35

**Photo 8 Debris around electric panel. Electric panel approx. 45ft from residents home.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 9 Storm water BMP: Partial culvert removed and drainage ditch and to opening of culvert not maintained at entrance to well site.**

**Photo 10 Storm water BMP: Culvert outlet and drainage ditch not maintained. Top of culvert exposed not proper cover at entrance to well site.**