

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 1 WH sign Weeds around well head**



**Photo 2 Weeds on well site**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 3** appears KPK has hooked up production lines from well head to vertical separator since last inspection and opened flow line valves.



**Photo 4 VENTING:** bubbles show what appears to be well head leaking at the tubing.



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 5 unused equipment: Unmarked not LOTO riser on flow line.**



**Photo 6 VENTING: bubbles show what appears to be well head leaking at the tubing.**



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 7 TRASH along TNK BTRY fence**



**Photo 8 Stained soil under Produced water load line.**



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 9 Stained soil around crude oil tank**



**Photo 10 stained soil around crude oil tank load line.**



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 11 stained soil around crude oil tank**



**Photo 12 Stained soil and mechanical issues on Vertical heated separator.**



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



Colorado Oil and Gas Conservation Commission  
Oct 1, 2019 12:53:36

**Photo 13 stained soil and mechanical issues on flow lines to vertical heated separator.**



Colorado Oil and Gas Conservation Commission  
Oct 1, 2019 12:53:59

**Photo 14 Weeds in and around TNK BTRY**

**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 15 Weeds On TNK BTRY site**



**Photo 16 Weeds on TNK BTRY site**



**Inspection Photos**  
**Location Name: Cleveland #2**  
**Location ID: 332884**



**Photo 17 TNK BTRY**

