

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**Location/API #: 067-07578**  
**Date: 9-24-2019**



Photo 1. View of western fill slope from the northwestern edge facing southward. Revegetation is largely comprised of smooth brome and gambel oak trees.



Photo 2. View of the project area from the northwestern corner facing center.



Photo 3. View of reference area vegetation, comprised of open grass field surrounded by mixed ponderosa pine and gambel oak woodland.