

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2019

Submitted Date:

10/01/2019

Document Number:

693900857**FIELD INSPECTION FORM**
 Loc ID 326556 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257076	WELL	PR	07/01/2013	GW	067-08295	HUBER 3-24	RI

General Comment:

On 9/24/2019, Catherine Roy conducted a followup reclamation and stormwater inspection. Review of well file indicates permission provided to Operator to allow a small portion of the interim reclamation area on document 2209470 to be used for wood cutting. Any other permissions in this regard would not be compliant with interim reclamation regulations. Therefore this corrective action from June 2019 is addressed. Corrective action to control stormwater erosion is partially addressed. See detail below and attached photos.

Inspected Facilities									
Facility ID:	257076	Type:	WELL	API Number:	067-08295	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Ditch and berm placed along access road appears to be installed in response to June 2019 corrective action. However, cobble "checks" placed in this manner are not installed in accordance with good engineering practices. See CDOT erosion control and stormwater quality field guide for examples. This will need to be carefully monitored and if erosion continues here additional BMPs will need to be installed using good engineering practices.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693900858	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4951849