



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Electric panel, transformers and meter box. Fabricated steel pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
		Comment:			
		Corrective Action:		Date:	
Ancillary equipment	# 1				
		Comment: Electric panel			
		Corrective Action:		Date:	
Bradenhead	# 1				
		Comment: Appears to be plumbed to surface			
		Corrective Action:		Date:	
Prime Mover	# 1				
		Comment: Electric motor			
		Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241692 Type: WELL API Number: 123-09481 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Tuesday 10/1/2019 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Milton H Nelson Unit C #1 KP Kauffman, at API #05-123-09481 in Weld County Colorado.                      While there, I observed Producing wellsite. This is a follow up inspection per Doc. # 693500926.                      During this inspection the following possible compliance issues appear to have been addressed:                      Rule 1003.f noxious weeds growing at location entrance. See photo #4.                      Rule 603.f Weeds around electric panel. See photo #3.                      Rule 210.e WH sign faded and needs to be replaced. See photo #2.                      Location is wet, weather is cloudy.                      No follow up on this site inspection needs to be conducted.                      Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	10/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300289	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4952020">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4952020</a>