

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/25/2019

Document Number:

679601640**FIELD INSPECTION FORM**

Loc ID 333001 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283277	WELL	PR	12/01/2011	OW	123-23630	STEVE J 18-9	PR
283401	WELL	PR	08/08/2006	GW	123-23651	STEVE J 18-23	PR
283402	WELL	PR	03/01/2019	OW	123-23650	STEVE J 18-10	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x3)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	2 Unused Gas meter houses. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/24/2019
Type	OTHER		
Comment:	Load out bucket has hole. See attached photo.		
Corrective Action:	Comply with Rule 605.e.	Date:	10/24/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' Chain link (x3)		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	6' chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLs	STEEL AST		40.399300,-104.822600	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance				
Earth	Adequate		Walls Sufficent		Base Sufficient		Adequate				
Comment:											
Corrective Action:									Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS				
PRODUCED WATER		3	OTHER	BV CONCRETE			,				
Comment:											
Corrective Action:									Date:		

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 60 BBLS	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with crude oil tanks.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	283277	Type:	WELL	API Number:	123-23630	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	283401	Type:	WELL	API Number:	123-23651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	283402	Type:	WELL	API Number:	123-23650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: [Erosion to location. See attached photos.](#)Corrective Action: [Install or repair required BMP's per Rule 1002.f.](#)

Date: 10/24/2019

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday, September 24, 2019 at approximately 13:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at STEVE J PAD (Noble Energy), at Location ID: 333001 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Load out bucket has hole. COMPLY WITH RULE 605.E. (Corrective Action Date: October 24, 2019) See attached photo #10. 2. (2) Unused gas meter house (disconnected) COMPLY WITH RULE 603.F. (Corrective Action Date: December 24, 2019) See attached photo #14. 3. Erosion to location. INSTALL OR REPAIR REQUIRED BMPs PER RULE 1002.F. (Corrective Action Date: October 24, 2019) See attached photo #11-13. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	09/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402188730	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946953
679601641	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946929